

MarlinFirmware / Marlin

[Code](#)[Issues 584](#)[Pull requests 42](#)[Actions](#)[Projects 1](#)[Security](#)[Releases](#)[Tags](#)

Marlin 2.0.9.1

[Latest release](#)[2.0.9.1 · b878127](#)[Compare ▾](#) **thinkyhead** released this 17 days ago

This maintenance release includes a number of fixes and improvements from contributors, testers, and co-developers.

Issues Fixed

- 🐛 Fix Air Assist ([#22159](#))
- 🧽 Extruders 0 patch for PWM Motor Current ([#22163](#))
- 🐛 Fix env validation for 1280/2560 boards ([#22150](#))
- 🐛 Fix MKS Robin E3 build ([#22149](#))
- 🐛 Fix IJK axis references, E stepper indices ([#22176](#), [906fa05](#))
- 🐛 Fix dual Neopixels ([#22174](#))
- 🐛 Fix heater display options/compile ([#22185](#))
- 🐛 Fix compact sensitive pins array ([#22184](#))
- 🐛 Redundant Temp Sensor followup ([#22173](#))
- 🐛 Fix LCD define typos ([927a1a1](#))
- 🐛 Define 'HEAD' axes for Markforged ([cce585f](#))
- 🐛 Fix Z_MULTI_ENDSTOPS + NUM_Z_STEPPER_DRIVERS 4 compile ([#22203](#))
- 🛠 Fix E.S.T. sanity-check errors ([#22224](#))
- 🐛 Trigger existing endstops on G38 hit ([4763116](#))
- 🐛 Fix Octopus build on case-sensitive FS ([#22206](#))

Improved / Optimized

- ✨ Update/extend Quiet Probing ([#22205](#))

LCD / Controller

- Update Russian language ([#22193](#))
- Update Ukrainian language ([#22183](#))
- Update Italian language ([#22182](#))
- MarlinUI Move Z >= 1000 ([#22192](#))
- Fix and enhance FTDI Eve Touch UI ([#22189](#), [#22223](#))

Hosts / Protocols

- Include 'H' value in M412 report ([#22138](#))

Boards / Pins

- TFT encoder pin for BTT GTR ([#22162](#))

General Cleanup

- Update probe heating value ([34066c1](#))
- Add G28 L description ([#22144](#))
- Cosmetic cleanup ([f2f23e8](#) , [651f15f](#) , [ec518e6](#) , [003ce25](#))
- Update TMC SPI endstops comment ([#22221](#))

5 6 8 13 people reacted

▼ Assets 2

- [Source code \(zip\)](#)
- [Source code \(tar.gz\)](#)

Marlin 2.0.9

2.0.9 -o- d7c7740

Compare ▾

thinkyhead released this 29 days ago

Marlin 2.0.9 is a progressive release featuring a major overhaul of the motion system. The number of linear axes can now be configured, allowing anywhere from one linear axis (X only) up to a total of six (X, Y, Z, U, V, W). The names of the axes can also be customized to your liking (barring conflicts with other G-code parameters).

New Features

- TMC Driver distinct baudrates ([#22008](#))
- Support for up to 6 linear axes ([#19112](#), [#22056](#), [#22068](#), [#22075](#), [#22094](#), [#22112](#))
- Add Laser Based I2C Ammeter Feature ([#21835](#), [#22079](#))
- More flexible redundant temp sensor ([#22085](#))
- Single Extruder with Dual Stepper Drivers ([#21403](#))
- Redundant Part Cooling Fan ([#21888](#))

New Machines and Boards

- BigTreeTech Octopus V1.1 ([#22042](#))

LCDs and Controllers

- Update Slovak language ([#22000](#))
- Fix and enhance FTDI EVE Touch UI ([#22047](#))
- Fallback ID for MKS TS35 V2.0 ([#22031](#))
- Reorganize FTDI Touch UI variants ([#22066](#))
- Fix and improve FTDI Eve Touch UI ([#22093](#))
- Update Hungarian language ([#22083](#))
- Fix ExtUI/DGUS Celsius display ([#22121](#))
- Include common TFT driver macros ([#22125](#))
- ExtUI "user click" and other tweaks ([#22122](#))
- MULTI_VOLUME for Color UI and MarlinUI ([#22004](#))

Optimized / Improved

- Refactor Linear / Logical / Distinct Axes ([#21953](#))
- Optimize Sensitive Pins array (except STM32) ([#22080](#))
- Home Z (and maybe XY) at the start of G35 ([#22060](#))

Fixed Boards / Pins

- Reorganize BTT_E3_RRF_INDEX_BOARD ([b99411b](#))
- Clean up stops, sdss pins ([dc202b3](#))
- Fix Creality v4 servo timer ([#22021](#))
- EEPROM options for BTT SKR 1.4 ([#22092](#))

- 🎨 Fix boot / SD for STM32 (F103Rx) boards ([#22087](#))
- 🔨 Robin Nano V3 overridable POWER_LOSS_PIN ([#22123](#))
- 🔨 Fix Serial+MSC for _USB envs ([#22116](#))
- 🔥 Remove Chitu default Touch Calibration ([#22133](#))

Issues Fixed

- 🐛 Fix usb-host-msc-cdc-msc issue ([#22025](#))
- 🐛 Fix Z endstop enum ([72b9f84](#))
- 🐛 Fix MMU compile with >5 EXTRUDERS ([#22036](#))
- 🐛 Fix M140 print job timer autostart ([#22046](#))
- ✨ Update G34 for 4x Z steppers ([#22039](#))
- 🍀 Patches for Zero Extruders (with TMC) ([82ea06e](#))
- 🐛 Fix small/huge I2C EEPROM address ([#22081](#))
- 🐛 Fix UBL 'R' parameter and adjust 'P' ([#22129](#))
- 🚒 Prevent BFT unaligned compressed data corruption ([#22134](#))
- 🐛 Prevent stepper sleep during long UBL idle ([#22137](#))

Configuration

- 🔧 Check G29_RETRY_AND_RECOVER requirements ([#21921](#))
- 🔧 Expose hidden BLTOUCH setting changes ([#22069](#))
- 🔧 Enforce BLTouch settings ([#22086](#))
- 🐛 Use whole PROBE_TEMP_COMPENSATION values ([#22130](#))

New HAL/STM32 Targets

- 🔨 Creality v4 with STM32 HAL ([#21999](#))
- 🐛 Fix env:STM32F103RE maple/unified split-up ([#22019](#))
- 🔨 MKS Robin E3 for HAL/STM32 ([#21927](#))
- 📦 STM32F103RE_btt(_USB) with HAL/STM32 ([#22040](#))
- 📦 Malyan M200 with HAL/STM32 ([#22052](#))
- 🐛 Include <EEPROM.h> in STM32 (for now) ([#22054](#))

Build / Upload

- 🔨 Use U8glib-HAL@~0.4.5 ([2505357](#))

- 🐛 Fix Probe Temp Calibration compile (#22032)
- 🔨 Move FLY_MINI env to stm32f1.ini (c207111)
- 🔨 Consolidate BTT linker scripts (62dc3e7 , #22038)
- 🐛 Fix STM3R / BEAST envs (#22028)
- 🔧 Update FYSETC E4 to espressif32@2.1.0 (#22049)
- 🔨 MightyBoard envs for Auto Build Marlin (#22100)
- 🔨 Envs for BTT SKR Mini with RET6 (512K) (#22050)
- 🏠 Refactor build encrypt / rename (#22124)

General Cleanup

- 📝 Update G61 comment (8f59d44)
- 🛡 Remove obsolete CUSTOM_SPI_PINS (#22058)
- 📝 Describe G12 XYZ (799a4ec)
- 🔨 Remove obsolete ON_BOARD_SPI_DEVICE (87344ae)
- 🎨 Clean up LPC1768 SPI init (fd3f7b3)
- 📝 Number SKR EXP headers (c221ee1)
- 🖌 Use #pragma once in pins files (9bf5cdd)
- 🎨 General cleanup of extui/dgus (d5510ea)

For Developers

- 🧑 Add caching to CI workflow (0e40d47)
- 🎨 32-bit float constants (STM32F1) (#21996)
- 🛠 Treat TPARA like SCARA in mfconfig (62a5957)
- 🎨 Adjust some conditionals (0e1e159)

  8  4  4  5  6 13 people reacted

▶ Assets 2

Marlin 2.0.8.2

🏷 2.0.8.2 ➔ 5b7b065

Compare ▾

 thinkyhead released this on May 29

Marlin 2.0.8.2 is a maintenance release with a number of small improvements and issues fixed.

This release adds `cap:HOST_ACTION_COMMANDS:0/1` to the `M115` extended capabilities report so hosts like OctoPrint can check for **basic** host-firmware interaction with `//action:` commands. For more complete interactivity you should enable `HOST_PROMPT_SUPPORT` and this will report `cap:PROMPT_SUPPORT:1` to the host.

New Machines and Boards

- Malyan M180 ([#21992](#))

New Features

- `MEDIA_MENU_AT_TOP` for MarlinUI ([#21925](#))
- Independent baud rates ([#21949](#))

Host and Protocol

- `cap:HOST_ACTION_COMMANDS` ([#21987](#))

Configuration

- Add `MESH_EDIT_MENU` sanity check ([#21922](#))

Board / HAL

- Fix BTT002 variant MMU2 serial pins ([#21980](#))
- Fix Selena Compact probe pin ([83f9413](#))
- Fix Octopus High Speed USB ([#21961](#))
- Fix MKS Robin E3 `BLTOUCH` and Fan PWM timer conflicts ([#21889](#))

LCD / Controller

- Update Polish language ([#21993](#))
- Improved SKR2 12864 LCD Delays ([#21956](#))
- Update ExtUI example ([f60965a](#))

Optimized / Improved

- LEDs refactor and extend ([#21962](#))
- Combined `M104 / M109` and `M140 / M190` code ([e573611](#))

Other Issues Fixed

- 🧩 Fix multi_volume + SDIO onboard compile (#21975)
- 🧩 Fix G29 K value (f1f622d)
- 🧩 Fix EEPROM_CHITCHAT (#21934)
- 🧩 Fix flowmeter calculation (#21959)
- 🧩 Fix wrong Z_ENDSTOP flag bit (#21963)
- 🧩 Fix Toshiba FlashAir (SDCARD_COMMANDS_SPLIT) (#21944)
- 🧩 Fix DELTA with SENSORLESS_PROBING

Build and Upload

- ⚡ PIO filters for M117 , M300 and M414 (#21972)
- 🧩 Fix envs using mks_encrypt.py (#21933)
- 🧩 Fix compile with PREVENT_COLD_EXTRUSION off (94e67a0)
- 🧩 Fix Teensy PINS_DEBUGGING compile (#21958)

For Developers

- 🎨 Macros for optional arguments (#21969)
- 🎨 Null heating message method (d1502f7)
- 🌱 Refactor axis homing/trusted state bits (57eeef65)
- 🌱 Minimize endstop bits (894c954)
- 🧑 Add a test for SAVED_POSITIONS (3220c49)
- 🌱 Refactor, comment endstop/probe enums (4dae589)
- 🎨 Flags for homing directions (e.g., Z_HOME_TO_MIN) (49b05ba)
- 📄 Document diveToFile , printListing (ddc82b8)
- 🌱 Simplify TMC utilities for more axes (765720e)
- 🌱 Refactor axis counts and loops (26a2443)

Maintenance

- 🎨 Apply shorthand and cleanups (7597b4f)
- 🎨 pause => pause_heaters (7cd0f2a)
- 🎨 Shorten lcd relative paths (3995e83)
- 🎨 Move HAS_EXTRUDERS (87a9437)
- 🎨 Update a condition (8e28731)

- Rename all/no axis enums ([cdbd438](#))
- MULTI_MANUAL => MULTI_E_MANUAL ([c977e82](#))
- Move switch sensor strings ([2de914c](#))
- Fix tests for EXTRUDERS 0 ([046bac6](#))
- Misc cleanup and fixes ([f7d28ce](#))
- Use defined strings ([c85633b](#))
- Add Configurations section to README ([#21955](#))



▶ Assets 2

Marlin 2.0.8.1

↳ 2.0.8.1 → [1dfa6cb](#)

Compare ▾

thinkyhead released this on May 15

This release patches various issues discovered since the 2.0.8 release and also includes some useful enhancements.

New Features

- M154 S Position Auto-Report ([#18427](#))
- Laser Cutter Air Assist ([#21753](#))
- ExtUI event for PID tuning start ([#21734](#))
- Echo LCD message to serial in kill
- UBL Mesh Wizard ([#21556](#), [#21791](#))
- Support a third serial port ([#21784](#))
- Instant Freeze/Resume Function ([#17462](#))

New Machines and Boards

- BigTreeTech SKR V2 Rev B ([#21805](#))
- BigTreeTech Octopus (STM32F446ZET6) ([#21826](#), [#21882](#), [#21883](#), [#21901](#))

Optimized / Improved

- Debounce for Power-Loss pin
- Optimize G-code flag parameters ([#21849](#))
- Move temp errors calling `kill()` out of ISR ([#21832](#))

Configuration

- Allow disable of `POWER_TIMEOUT` ([#21771](#))
- Allow Creality V4 SERVO0 and PROBE pin overrides ([#21770](#))
- `SOFT_RESET_VIA_SERIAL` sanity-check
- Better error message for bad array sizes
- Fix `G29_RETRY_AND_RECOVER` dependency ([#21907](#))
-  Improve `SD_DETECT_STATE` default ([#21885](#))
- Update Advanced Pause description ([#21829](#))
- Fix multi volume config typo ([#21880](#))
- Make `[XYZ]_ENABLE_PIN` an optional pin ([#21801](#))

LCD / Controller

- Capacitive Touch Screen (GT911) for SKR SE BX ([#21843](#))
- Add `MKS_LCD12864B`
- Fix E3V2 Control Menu icon/text order ([#21838](#))
- Fix MKS UI missing font select condition ([#21905](#))
- Fix Nextion compile error ([#21884](#))
- Active MMU slot indicator ([#21842](#))
- TFT pins for BTT GTR V1
- TFT SPI for BTT SKR v1.3 ([#21794](#))
- Update SKR 1.3 touch pins
- Update Robin Pro TFT Pins ([#21879](#), [#21900](#))

Build and Upload

- BigTreeTech SKR Mini E3 with HAL/STM32 ([#21488](#))
- Only look for target disk during Upload ([#21804](#))
- Update STM32 platform to 12.1
- Use `adafruit/Adafruit_NeoPixel@~1.8.0`
- Update `FLSUN_HISPEED` env to `f1sun_hispeedv1` ([#21510](#))

For Developers

- Move ExtUI subfolders up a level ([#21820](#))
- Add and apply `REPEAT_1` macro
- Apply SBI/CBI/TEST in HAL
- Additional utility macros
- Simplify macro expansion with recursion ([#21859](#))
- Better `opt_set` comment of old val
- Simplify / undef extra endstops ([#21808](#))

General Issues Fixed

- Fix "undefined abl_points" error
- Fix `SDCARD_CONNECTION` default for BTT SKR ([#21755](#))
- Fix Singlenozzle Standby issues ([#21759](#))
- Fix Power-Loss Save on Pause ([#21749](#))
- Fix Z raise in filament load `M701` ([#21762](#))
- Add missing ExtUI method ([#21763](#))
- Fix parser temperature rounding
- Fix bad call to 'diskIODriver' ([#21775](#))
- Fix bad DELTA probe move ([#21781](#))
- Fix `flush_and_request_resend`
- Prevent watchdog reset in `setup()` ([#21776](#))
- Pause and PLR refinements
- Fix MMU2 compile with include ([#21809](#))
- Update `chart.js` to 2.9.4 for e4d@box UI
-  Fix version reference
-  Fix excessive MMU2 timeout ([#21855](#))
- `G60 - G61` Save E position ([#21810](#))
- Patches for `CASE_LIGHT_USE_RGB_LED` ([#21811](#))
- Let `M421 C` select any point
- Always prompt in `M125` if host-prompt (as with Ext UI) ([#21828](#))
- Lerdge K EEPROM and TFT ([#21812](#))
- Consider SD print complete only when commands are done ([#21840](#))
-  Fix Lerdge USB Flash Drive envs ([#21847](#))

- Unify BTT Motor Expansion Options ([#21823](#))
- Fix and improve Power-Loss Recovery ([#21779](#), [#21894](#))
- Fix L64xx init for Z4 axis
- 🐛 Fix G5 IJ with Motion Mode ([#21858](#))
- Fix compilation failure in M1001 ([#21897](#))
- 🐛 Fix Realtime Reporting with Motion Modes ([#21902](#))



▶ Assets 2

Marlin 2.0.8

🏷 2.0.8 -o d92decb

Compare ▾

 thinkyhead released this on Apr 30

New Features

- Tool sensors ([#17239](#))
- Z Probe Offset Wizard ([#18866](#), [#19647](#), [#19742](#), [#20167](#), [#20239](#), [#20344](#), [#20414](#), [#20439](#))
- G34 Mechanical Gantry Calibration (like Prusa M915) ([#18972](#))
- Swedish language for MarlinUI ([#20826](#))
- Custom move feedrate for G26 ([#20879](#))
- Chamber servo vent, auto fan ([#19519](#), [#21594](#))
- Support for Debug Codes - Dnnn ([#19225](#), [#19697](#))
- REPORT_TRAMMING_MM option ([#19682](#))
- Power-on/off G-code options ([#19837](#))
- SPINDLE_SERVO option ([#19971](#))
- POWER_OFF_DELAY option ([#19987](#))
- ASSISTED_TRAMMING_WAIT_POSITION ([#20063](#))
- HOME_Z_FIRST option ([#20113](#))
- SMUFF (MMU2 clone) support ([#19912](#))
- Allow cold Filament Load/Unload with M302 P1 ([#20262](#))
- Level Corners with Probe option ([#20241](#))
- M808 Repeat Markers / "End Repeat Loops" menu item ([#20084](#))

- Make M220 B / R parameters standard ([#20355](#))
- Probe Tare, Probe Activation Switch ([#20379](#), [#20550](#))
- Laser Test Fire ([#20452](#))
- NO_SD_DETECT option ([#20741](#))
- "MeatPack" ([OctoPrint plugin](#)) serial encoding ([#20802](#), [#20893](#), [#20896](#), [#20903](#), [#21306](#), [#21336](#))
- STM32 Shared Media - USB Mass Storage Device ([#20956](#))
- Postmortem Debugging to serial port ([#20492](#))
- Chamber Heater PID ([#21156](#))
- PROBING_HEATERS_OFF sub-option WAIT_FOR_HOTEND ([#20835](#))
- Preheat Menu shortcut option ([#20350](#))
- RGB Caselight ([#20341](#))
- Filament Runout handling for Mixing Extruder ([#20327](#))
- G-code Digital Buttons ([#18389](#), [#21284](#))
- Cooler (for Laser) - M143 , M193 ([#21255](#))
- Add M207 / 8 / 9 reporting ([#21335](#))
- Custom menu items confirm option ([#21338](#))
- TPARA - 3DOF robot arm IK ([#21005](#), [#21248](#))
- Hilbert space-filling curve for UBL / G26 ([#21387](#), [#21453](#), [#21480](#))
- Extend M106 / M107 for better laser module support ([#16082](#))
- Laser Coolant Flow Meter / Safety Shutdown ([#21431](#), [#21498](#), [#21573](#))
- Multi-Volume. Select Media for LVGL ([#21344](#))
- Realtime Reporting, S000 , P000 , R000 ([#19330](#), [#21630](#))
- M10 - M11 Air Evacuation for Spindle/Laser ([#21668](#))
- Soft Reset via Serial or post-kill button click ([#21652](#))
- Backlash Compensation for COREnn ([#21612](#), [#21731](#))
- Stepper Driver Anti-Reverse Protection ([#21503](#))

New Machines and Boards

- Anet ET4 / ET4P and Anet TFT28 / TFT35 ([#20280](#))
- BigTreeTech E3 RRF
- BigTreeTech SKR CR6 ([#20522](#))
- BigTreeTech SKR Mini MZ V1 ([#19818](#), [#20069](#))
- BigTreeTech SKR V2.0 ([#21503](#), [#21717](#), [#21741](#))

- BigTreeTech SKR-SE-BX (STM32H743IIT6 ARM Cortex M7) and BIQU_BX_TFT70 ([#21536](#))
- Creality v4.2.10 board ([#20647](#))
- Creality v4.3.1 (Ender 6) board ([#20512](#))
- Creality v4.5.2 ([#20378](#))
- Creality v4.5.3 (CR-6 SE, CR-6 MAX) ([#20468](#))
- Eryone Thinker V2 ([#21190](#))
- FLSUN Delta QQS-Pro ([#19793](#))
- FLY CDY ([#19979](#))
- FLY MINI ([#19185](#))
- FYSETC Cheetah 2.0 ([#20897](#))
- FYSETC E4 ([#20032](#))
- FYSETC Spider ([#21458](#))
- KRATOS32 / K.32 board and LCD controllers ([#21334](#))
- Longer LK Pro / Alfawise PRO ([#20185](#), [#20372](#))
- MKS Robin E3 / E3D v1.1 ([#20216](#))
- MPX_ARM_MINI board (Mingda MD-16) ([#20711](#))
- NUCLEO-F767ZI dev board ([#19373](#))
- Ramps-S v1.2 ([#19815](#))
- SMART RAMPS 1.4 with Mega2560 ([#21059](#), [#21128](#))
- Zonestar Z8 XM2 ([#19991](#))

Configuration Updates

- Ensure A4988 for unspecified driver type ([#19798](#))
- Allow MAX31865 resistance values configuration ([#19695](#))
- TFT Presets, Generic options, Sanity checks ([#19723](#))
- Default `LASER_POWER_INLINE` to OFF ([#19727](#))
- Distinct Chopper Timing settings ([#19781](#), [#19850](#))
- Longer3D: `LONGER_LK_TFT28` now set by config ([#19817](#))
- Configure TMC interpolation per driver ([#19828](#))
- Guards for large `BLOCK_BUFFER_SIZE` (>=128) ([#20130](#))
- Allow dummy thermistors without pin definitions ([#20159](#), [#20247](#))
- Add Thermistor 20-21 notes ([#19246](#))
- Permit touch calibration override
- Optional `M42` / `M226` ; Add more features filters ([#19664](#))

- Option to prevent (extra) Watchdog init on STM32 ([#19693](#))
- Sanity-check mutually-exclusive G34 features ([#19706](#))
- Add HAS_MEDIA_SUBCALLS to enable/disable M32
- Option to ignore SD at startup ([#20099](#))
- Option to open the File Browser on Media Insert ([#20151](#))
- Use MANUAL_PROBE_START_Z for UBL manual probing ([#20160](#))
- Proper pullup/pulldown configurability ([#20242](#))
- No Z_MULTI_ENDSTOPS when HOMING_Z_WITH_PROBE ([#20254](#))
- Group related homing options ([#20283](#))
- Leveling Fade Height default setting ([#20316](#))
- Clarify Delta & SCARA config location ([#20403](#))
- Clarify "not Interrupt-capable" error message ([#20419](#))
- Add Z_SENSORLESS sanity checks ([#20421](#), [#20438](#))
- SHORT_MANUAL_Z_MOVE is now FINE_MANUAL_MOVE
- Option to always enable leveling after G28
- Minimum temp options for Probing and G12 Nozzle Clean ([#20383](#))
- Improve STM32 timer conflict messages ([#20544](#))
- Add OPTIMIZED_MESH_STORAGE option (for UBL) ([#20371](#))
- Validate defined probe points ([#20572](#))
- Allow define of HOMING_FEEDRATE_(XY|Z)
- Apply SHOW_BOOTSCREEN to TFT_COLOR_UI ([#20586](#))
- Clarify sanity-check for custom status bitmap ([#20588](#))
- Adjustable precision in M105 temperature report ([#20602](#), [#20687](#))
- Multi-Z stepper inverting ([#20678](#))
- Configurable Corner Leveling point order ([#20733](#))
- USE_M73_REMAINING_TIME sanity-check ([#20751](#))
- Configure / disable PRINTCOUNTER save interval ([#20856](#))
- Configure / disable PRINTCOUNTER save interval ([#20856](#))
- Touch Calibration Screen auto-save option ([#20971](#))
- Allow Zero Endstops (e.g., for CNC) ([#21120](#), [#21188](#))
- Combine Z_AFTER_DEACTIVATE with UNKNOWN_Z_NO_RAISE ([#20444](#))
- Renamed some " SPEED " options as " FEEDRATE " ([#21217](#))
- Default microsteps to axis first stepper ([#21230](#))
- Safe Z homing for Power Loss Recovery ([#16909](#))

- Extend Heater Overshoot Options ([#21273](#))
- Undef unused 2nd serial option(s) ([#21331](#))
- Sanity-checks for NOZZLE_CLEAN_FEATURE ([#21332](#))
- Main / Config Custom Submenus ([#18177](#))
- Better chopper defaults
- More detailed serial config error
- Sanity check MIXING_EXTRUDER + DISTINCT_E_FACTORS ([#21689](#))
- Make Cancel Objects reporting optional ([#21698](#))

Optimized / Improved

- Fix various errors, warnings in example config builds ([#19686](#))
- Add loose soft endstop state, apply to UBL fine-tune ([#19681](#))
- If needed, home before G34 ([#19713](#))
- Handle M410 in the main task ([#19752](#))
- Fix Color UI external_control, wait_for_release ([#19771](#))
- Fix HAL/STM32 FastIO for analog pins ([#19735](#))
- Fix G35 PROGMEM strings ([#19926](#))
- Handle UTF in long filenames ([#20087](#), [#20115](#), [#20121](#), [#20135](#))
- G34 z stepper locking ([#20091](#))
- Optimize M360
- Update IDEX menus, add post- M605 event G-code ([#20133](#))
- Reduce RAM usage for TFT Color UI on SGen-L ([#20179](#))
- Abort print on media removal ([#20200](#))
- Skip unnecessary (costly) SW Stepper Enable ([#20218](#))
- Allow Status Message without LCD ([#20246](#))
- Optimize emergency parser check
- On pause release the extruder for easier filament change ([#20346](#))
- Fix, improve Tramming Wizard behavior ([#20437](#), [#20796](#))
- MAX Thermocouples rework ([#20447](#))
- Support RGBW on PCA9632 ([#20455](#))
- Preheat *before* Power Loss Recovery homing ([#20697](#))
- Support up to 6 Tramming points ([#20720](#), [#21646](#))
- Init KILL, SUICIDE, PSU earlier ([#20810](#))
- Init serial ports first ([#20944](#))

- Improve probe preheat behavior ([#21033](#))
- Use 'H' value for UBL G29 z-clearance ([#21114](#))
- Fix and improve G-code queue ([#21122](#))
- Pause SD queue early on M25 ([#21317](#))
- Add reporting to M207 / 8 / 9 ([#21335](#))
- Optimize MarlinSettings with template methods ([#21426](#))
- Optimize LSF for size, efficiency ([#21443](#))
- Optimize BLTouch code for size ([#21477](#))
- Generalize MMU ([#21469](#))
- Move last bootscreen delay to end of setup ([#21665](#))
- Use temp_info_t for temp_redundant ([#21715](#))

Board / HAL Updates

- Retire HAL for STM32F4 / F7 ([#20153](#))
- Improved MKS Robin support ([#19333](#))
- Minor SPI fixes, systick_callback for STM32F1 HAL compatibility ([#19565](#))
- Update MKS SGen-L V2 RGB LED pins ([#19762](#))
- Teensy 4.1 Ethernet support ([#19801](#), [#21316](#))
- Ignore NativeEthernet on AT90USB1286 ([#19885](#))
- AZTEEG X5 mini LED pins ([#19909](#))
- Generalize BTT SKR E3-DIP version ([#19910](#))
- Rename, adjust Dagoma F5 ([#19947](#))
- FAST_PWM for STM32F1 ([#19952](#))
- FAST_PWM for STM32 ([#20025](#))
- Get STM32 clock rates from framework ([#19978](#))
- HAL support for 8s watchdog
- Standardize Marlin SPI ([#19989](#))
- STM32F1 cleanup, incl. SoftwareSerial removal ([#20046](#))
- BTT SKR driver expansion board ([#20088](#), [#20123](#))
- Allow overriding servo pin for MKS Robin Mini ([#20158](#))
- FLSun Hispeedv1 Board update ([#19959](#))
- Migrate Hispeedv1 (QQS-Pro) to HAL/STM32 ([#20354](#))
- Use RTD for MAX31865 reading ([#20188](#))
- Add BTN_ENC_EN for many boards ([#19796](#), [#19890](#), [#20684](#))

- SKR E3 Turbo Controller Fan ([#20320](#))
- Permit SD EEPROM emulation on Ender-3 V2 ([#20353](#))
- Suspend Servos for STM32+NeoPixel ([#19963](#))
- SPI TFT for STM32F4 boards ([#20384](#))
- MKS Robin Pins fixes for STM32 and STM32F1 ([#20404](#))
- Add `HAS_PIN_27_BOARD` for `CREALITY_V4` ([#20446](#))
- MKS Robin Nano V3 and STM32F4x0Vx Variant ([#20430](#), [#21174](#), [#21238](#))
- Let boards set Default TMC Slave Addresses ([#20498](#))
- 12-bit ADC resolution for STM32 ([#20519](#), [#20562](#))
- Overrides to prevent STM32 timer conflicts ([#20545](#))
- Unify FYSETC F6 1.3 / 1.4 ([#20507](#))
- Better defaults, compatibility for SDIO + STM32 ([#20570](#), [#21440](#))
- USB Flash Drive via native USB Host + MSC ([#20571](#))
- Prefix SD SPI pins (SCK, MISO, MOSI, SS) ([#20606](#))
- Define SANGUINOLOLU 1.1 enable pins ([#20682](#))
- Wanhao One+ SD Detect pin ([#20724](#))
- ESP32 Tone Generator ([#20704](#))
- `NEOPIXEL` overridable on BTT SKR ([#20797](#))
- FYSETC_242 OLED 12864 for S6 ([#20767](#))
- Lerdge K/S/X support for Flash Drive ([#20593](#))
- Add labels, condition for BTT GTR M5 pins ([#20772](#))
- Updated display timing for SKR Pro ([#21346](#))
- ZONESTAR_LCD warning for RAMPS / ReARM ([#20702](#))
- Refactor serial class with templates ([#20783](#), [#21249](#), [#21287](#), [#21318](#))
- Allow SERVO0_PIN override on Creality Melzi ([#21007](#))
- EXP headers for RAMPS 1.x ([#21054](#))
- Trigorilla Pro: Allow for swapped Z-stops
- Add `BOARD_PREINIT` (for Longer3D open drain pins) ([#21159](#))
- Lerdge-K TMC 2208/9 UART pins ([#21299](#))
- Lerdge-X I²C EEPROM pins, size ([#21322](#))
- Update display timing for SKR Pro ([#21346](#))
- Update Anet V1.0 display timing ([#21425](#))
- GT2560 Rev.A Plus Z Max Pin with BLTouch ([#21375](#), [#21512](#))
- Board IDs for G2560 Rev B, G2560 v4, GTM32 VD ([#21499](#))

- EXP2_01_PIN for BTT BTT002 1.0
- Changes supporting "Prussia3D" MK3 ([#21617](#))
- MCP4451 Digipot Support for Azteeg X5 GT ([#21680](#))

Board / HAL Fixes

- Fix onboard SD card support for Teensy 3.6 & 4.1 ([#19593](#))
- Fix TEMP_ADC_PROBE support for STM32F1 ([#19582](#))
- Fix Archim1 stepper timing (with new variant) ([#19596](#))
- Fix HAL/STM32 FastIO for analog pins ([#19735](#))
- Fix Smoothieboard digipots i2c pin ([#19784](#))
- Fix TMC serial port for FYSETC AIO_II ([#19842](#))
- Fix BTT002 PeripheralPins PWM assignments ([#20036](#))
- Fix E4d@box pins, stepper i2s ([#20055](#))
- Fix FYSETC S6 timer conflict ([#20044](#))
- Fix FYSETC S6 I2C EEPROM size ([#20340](#))
- Fix FYSETC_S6 heaters pins ([#21483](#))
- Fix SKR E3 DIP pin CLCD_SPI_CS ([#20078](#))
- Fix GTR NeoPixel pin with FYSETC Mini12864 ([#20203](#))
- Fix BTT GTR 1.0 endstop/DIAG pins ([#20296](#))
- Fix and optimize MightyBoard ([#20493](#))
- Fix Creality EEPROM watchdog freq. ([#20510](#))
- Fix TMC220x short circuit ([#20731](#))
- Fix Trigorilla Pro STOP pins ([#20801](#))
- Fix ESP32 I2S init placement ([#21019](#))
- Fix mini12864 v2.1 + PSU control + NeoPixel backlight ([#21021](#))
- Fix STM32F1 emergency parser ([#21011](#))
- SAMD51: Respect serial buffer size ([#21194](#))
- Fix SKR E3 Mini V2.0 Fan Bug ([#21079](#))
- Fix and add STM32 SDIO DMA ([#21476](#))
- Add E1 pins for RAMPS 1.4.4 / AGC
- Fix Grand Central SD dependency ([#21660](#))

New LCDs / Controllers

- Two additional EVE displays ([#18839](#))

- Support 4.3" (480x272) Color UI display ([#20334](#))
- LVGL and Classic UI for STM32 ([#20552](#))
- MKS H43 controller ([#20609](#), [#21240](#), [#21267](#), [#21388](#), [#21485](#), [#21500](#), [#21511](#), [#21619](#))
- Nextion TFT touch screen ([#21324](#))
- New-style Anycubic Chiron TFT ([#21597](#))

New LCD / Controller Features

- Add Touch Calibration screen ([#20049](#), [#20454](#), [#20524](#))
- "Sound: ON/OFF" menu item ([#19901](#))
- Fysetc Mini 12864 + GT2560 A(+) ([#19878](#))
- Multi-platform DWIN_CREALITY_LCD support ([#20738](#))
- Touch UI support for X2, Y2 and Z2 ([#19538](#))
- Implement wait_for_user for Color UI ([#19694](#))
- ANET_FULL_GRAPHICS_LCD_ALT_WIRING for SKR 1.4 ([#20011](#), [#20427](#))
- Anet 1.0 alternative graphical LCD wiring ([#20022](#))
- Color UI single touch menu navigation ([#20053](#))
- Tramming Wizard submenu option ([#20000](#))
- COLOR_UI without TOUCH_SCREEN  ([#20178](#), [#20269](#))
- Remaining Time for Prusa-style LCD layout ([#20148](#))
- TFTGLCD support for STM32F1xx ([#20515](#))
- Small / Large Bootscreen option for TFT_COLOR_UI ([#20578](#))
- LVGL G-code preview ([#20589](#), [#20564](#))
- MKS WiFi for TFT_LVGL_UI ([#20191](#))
- LVGL UI G-code console ([#20755](#))
- LVGL "more" menu ([#20940](#), [#21004](#))
- Mesh Editor for FTDI Eve Touch UI ([#21381](#))
- MKS LVGL UI: Display/edit fan percentage ([#21544](#))
- E3V2 DWIN Advanced Settings menu ([#21534](#), [#21700](#))
- Color UI Move Screen for 320x240 TFT ([#21708](#))

LCD / Controller Updates

- Update French language ([#20472](#))
- Update Hungarian language ([#20996](#), [#21266](#), [#21407](#))
- Update Italian language ([#19654](#), [#19953](#), [#20480](#), [#20551](#), [#20663](#), [#20789](#), [#21537](#))

- Update Russian ([#20508](#), [#20529](#))
- Update Ukrainian ([#20508](#), [#20668](#))
- Update Slovak language ([#19561](#), [#20181](#), [#21224](#))
- Add Spanish translations ([#20020](#))
- TFT Refactoring ([#19192](#))
- Provide FYSETC F6 v1.3 LCD pins for HD44780 ([#19769](#))
- Color UI for MKS SGen-L V2 ([#19919](#), [#20209](#))
- Color UI circular task queue ([#19918](#))
- Reset calibration screen touch timer on click ([#19951](#))
- Y-center GLCD status logo, reorganize ([#19954](#))
- Increase SPI Speed on LPC. Color and Classic UI for MKS SGEN L. ([#19945](#))
- Show un-mounted media slot ([#20005](#))
- Better Classic UI touch resolution ([#20004](#))
- Use status bitmaps based on `LCD_FIRST_TOOL`
- Better edit range for Linear Advance K ([#20155](#))
- Reapply superscript substitution ([#20219](#))
- Clear menu history for browse media on insert ([#20236](#))
- Display position on LCD in current units ([#20145](#))
- Set "`lcd_move_e`" index to fix the label ([#20263](#))
- Shorter Filament Load/Unload Strings to fit Graphical Display ([#20369](#))
- Allow BTT EXP-MOT be used with 10-pin (EXP1) displays ([#20396](#))
- Move ExtUI ABL mesh edit, limit to bilinear ([#20381](#))
- Cutter Power in percent format ([#20410](#))
- Legacy MKS WiFi Cura plugin compatibility ([#20589](#))
- Assisted Tramming improvements ([#20298](#))
- 4 / 5 digits for some edit items ([#20793](#))
- Color UI Multi-language support ([#20725](#), [#20915](#), [#20972](#))
- Increase filament runout distance edit limit ([#20828](#))
- `lcd_put_wchar_max` for COLOR_UI ([#20838](#))
- ZONESTAR_LCD warning for RAMPS / ReARM ([#20702](#))
- Graphical TFT fixes, cleanup ([#20861](#))
- KILL, BEEPER pins for LCD_FOR_MELZI ([#20924](#))
- Refresh screen on M22 (detach) ([#20958](#))
- Re-calibrate touch after EEPROM reset, if needed ([#20934](#))

- Fix and extend FTDI EVE Touch UI (#20393, #20466, #20517, #20518, #20532, #20549, #20987, #21232, #21148, #21167, #21487, #21607)
- Ender 3 V2 display improvements (#20983, #21072, #21369, #21035)
- Support for FYSETC mini12864 with BTT002 (#21096)
- Support for YHCB2004 with GT2560 v4.1B (#21091, #21111, 21450, #21472)
- Clean up, optimize ExtUI/TFT code (#21333)
- MKS UI: Monitor state when idle (#21452)
- Update u8g / AVR display timing defaults (#21518)
- Touch UI Bed Mesh Screen refactor, enhancements (#21521)
- Delay U8glib init using U8glib-HAL 0.4.4 (#21496)
- Space-separate scrolling Status Message (#21523)
- ExtUI::onPostprocessSettings (#21683)

LCD / Controller Fixes

- Fix Move Screen with disabled Touch (#19558)
- Restore ° (degree symbol) to 6x9 small info font (#19645)
- Fix screen click reading too often (#19696)
- Fix Anycubic i3 Mega target temperature display (#19572)
- Fix German translation purging/unloading (#19615)
- Use LiquidCrystal_I2C@1.1.4 for RA_CONTROL_PANEL (#19875)
- Fix Tune/Fan edit items
- Fix "autotune" LCD message (#20127)
- Fix and improve Ender-3 V2 (#19642, #20324, #20338, #20352, #20443, #20526, #20837, #21272)
- Fixes for TFTGLCD Panel, FastIO (#19614)
- Fix UTF8 handling for Color UI (#19708)
- Fix and optimize MKS UI (#19869, #20813)
- Fix some LVGL bugs (#19900, #19904, #20214)
- Fix 320x240 touch buttons Y (#20079)
- Fix Filament Change menu items (#20201, #20565)
- FIX TMC menu message (#20294)
- Fix "back" location for Level Bed Corners
- Fix Spindle/Laser Control menu (#20347)
- Fix ZoneStar LCD 2004 buttons (#20489)

- Fix DOGM status message scrolling ([#20557](#))
- Fix ST7920 timing for Rumba32, Fysetc S6 ([#20556](#))
- Fix Menu Mixer for Color UI ([#20566](#))
- Fix SD SPI Speed override, FTDI mesh edit ([#20657](#))
- Fixes for TFTGLCD ([#20734](#))
- Fix Anycubic Chiron TFT issues ([#20807](#), [#21152](#), [#21183](#))
- Fix Ender 3 V2 unwanted E motion on manual moves ([#20806](#))
- Fix MKS SGen-L with FYSETC_MINI_12864 LCD ([#20998](#))
- Fix AZSMZ_12864 on SMART RAMPS ([#21056](#))
- Fix MKS LVGL UI Main screen / buttons / icons ([#21468](#), [#21595](#))

Serial / Host Updates

- G35 workaround for Pronterface "feature" ([#19577](#))
- Fix M503 output for M907 motor current ([#19777](#))
- Fresh Web GUI (based on bootstrap.js) ([#19812](#))
- Help hosts when Marlin is password-locked ([#20348](#))
- Fix " //action " prefix ([#20600](#))
- Fix M48 output ([#20713](#))
- Fix reporting of TMC_S2VSA/B ([#20730](#))
- Improve RPi host kernel panic mitigation
- Refactor Serial ports for more flexibility
- Enable Purge More / Resume with EP + Host Prompt ([#21671](#))

General Issues Fixed

- Ignore M22 during SD print
- Fix G2 / G3 arcs over 180° ([#20292](#), [#20314](#), [#20322](#))
- Improve plan_arc circle detection ([#20440](#))
- Fix Buzzer (pin) init for uninitialized FastIO ([#19559](#))
- No move on Park = No move on Resume ([#19569](#))
- Fix compile of MMU2 with S-mode disabled ([#19584](#))
- Fix Z_AFTER_HOMING without probe ([#19607](#))
- Allow bypass for cold E movement ([#19606](#))
- Keep HAL tasks running during PID Autotune ([#19671](#))
- Fix starting fan with bad material preset index ([#19773](#))

- Watchdog Refresh for LVGL Asset Load ([#19724](#))
- Fix `SET_SOFT_ENDSTOP_LOOSE` w/out soft endstops ([#19734](#))
- Fix IDEX layer shift and DIR states ([#19756](#))
- Apply home offsets to probing, Z Safe Homing ([#19423](#))
- Fix `G2 / G3 P<circles> E` and Z motion ([#19797](#))
- Fix Anycubic Chiron "Ready" detection ([#19880](#))
- Fix Chiron probe low point ([#19962](#))
- Fix PASSWORD compile w/out LCD ([#19888](#))
- Fix DAC-related bugs ([#19907](#), [#19921](#), [#20205](#))
- Keep SPI active on LPC176x ([#19932](#))
- Fix Laser / Spindle issues ([#19970](#), [#20509](#))
- Fix STM32 HW Serial + EP compile ([#19990](#))
- Don't close diveDir in fileExists ([#20035](#))
- Fix Endstop Interrupts with SPI endstops, sanity checks ([#20051](#))
- Fix tool-change servo index for E2 and up ([#20060](#))
- Use extra `G35` BLTouch HS Mode clearance in Tramming Wizard ([#20057](#))
- Fix Linux GPIO logging ([#20093](#))
- Fix MAX6675 SPI init, conflicts ([#20086](#))
- Fix MAX31865 on SPI (PT100/1000) support ([#20074](#))
- Fix extraneous Linear Advance DIR change ([#20131](#))
- Multi-Hotend Preheat Fixes ([#20165](#))
- Fix `NaN` mesh entries with `ABL_BILINEAR_SUBDIVISION` ([#20143](#))
- Fix bad `SET_FAST_PWM_FREQ` calls ([#20227](#))
- Fix backward Filament (Presence) Sensor pulls ([#20228](#))
- Fix Load Filament wait ([#20243](#))
- Fix UBL manual mesh adjust behavior ([#20248](#))
- Fix `z4` in `ENABLE / DISABLE_AXIS_Z` ([#20256](#))
- Add missing header to use `HAS_SD_HOST_DRIVE` ([#20270](#))
- Fix `M73` LCD code typo ([#20300](#))
- Prevent Watchdog reset writing Creality 4.x EEPROM ([#20328](#))
- Fix `MESH_BED_LEVELING` without `SEGMENT_LEVELLED_MOVES` ([#20363](#))
- Fix `TMC_HOME_PHASE` divide-by-zero ([#20368](#))
- Fix `auto#.g` file handling, add `NO_SD_AUTOSTART` ([#20071](#))
- Fix UBL Debug Messages ([#20423](#))

- Fix issues with preheating before leveling
- Fix SD print completion logic ([#20456](#))
- Fix RESTORE_LEVELING_AFTER_G28 behavior ([#20471](#))
- Apply HOME_AFTER_DEACTIVATE to G28 O ([#20525](#))
- Fix G34 compile with bed leveling disabled ([#20537](#))
- Fix UBL mesh inset Z position ([#20538](#))
- Fix G28 leveling state, UBL compile ([#20499](#))
- Apply NO_MOTION_BEFORE_HOMING to joystick motion ([#20462](#))
- Fix PARKING_EXTRUDER homing with solenoid ([#20473](#))
- Fix CHAMBER_FAN_MODE 0 build ([#20621](#))
- Fix UBL mesh edit delta moves ([#20620](#))
- Fix thermal error protection, reporting ([#20655](#))
- Fix IDEX reboot on travel after G28 X ([#20654](#))
- Defer "quiet probing" till the last Z bump ([#20610](#))
- Don't apply hotend_offset.z to Z soft endstops ([#20675](#))
- MMU2 as a standard serial device ([#20771](#), [#20794](#), [#20811](#))
- Raise Z on exit from 'Level Bed Corners' ([#20817](#))
- Remove extra G29 V newlines ([#20955](#))
- Fix ARM delay function ([#20901](#))
- Fix TEMP_0_TR_ENABLE, rename temp conditions ([#21016](#))
- Fix: Unsupported use of %f in printf ([#21001](#))
- Fix remaining time divide-by-zero ([#21080](#))
- Fix IDEX broken endstop test ([#21110](#))
- Fixes for MP_SCARA ([#21113](#), [#21686](#))
- Fix cleaning_buffer_counter check ([#21115](#))
- Fix LEVEL_CORNERS_USE_PROBE with BLTOUCH_HS_MODE ([#21161](#))
- Init (stow) BLTouch before X/Y homing ([#21192](#))
- Fix M355 with NEOPIXEL ([#21200](#))
- Fix GTR / SKR PRO + USB Flash Drive build ([#21197](#))
- Fix M876 when called from EP ([#21210](#))
- Duplicate fan speed in M106 / 7 IDEX Duplication Mode ([#21208](#))
- Apply AUTO_POWER_CONTROL later in setup() ([#21193](#))
- Fix Host Keepalive serial target ([#21283](#), [#21290](#))
- Fix LPC + TMC boot loop ([#21298](#))

- Fix TouchMI stow in G34 ([#21291](#))
- Fix password menu stickiness before first auth ([#21295](#))
- Un-pause fans on STOP
- Fix macros that call macros crashing ([#21383](#))
- Apply endstops-always-on for G28 sensorless ([#21441](#), [#21442](#))
- Avoid watchdog reset in all wired EEPROMs ([#21436](#))
- Remove extraneous 'extern' hints ([#21516](#))
- Fix FAT delete of items with longname ([#21528](#))
- Make `DELAY_NS` round up on AVR ([#21546](#))
- Park Magnetic Switching Toolhead at the very end ([#21552](#))
- Fix M114 E / R broken by LIN_ADVANCE ([#21579](#))
- Fix Resume Print with UBL ([#21564](#))
- Fix Max Temperature not enforced ([#21592](#))
- Fix and improve Power Monitor ([#21551](#))
- Always swap with PRIME_FIRST_USED disabled ([#21622](#))
- Don't display service prompt unless needed ([#21654](#))
- Prevent extrusion on M600 un-park ([#21670](#))
- Fix Thermal Runaway false-alarm in M303 , add HeaterWatch::check ([#21743](#))
- Fix compile with DISTINCT_E_FACTORS + SLIM_LCD_MENU ([#21733](#))

Build and Upload

- Fix 'bossac' upload on Windows ([#19545](#))
- Fix and improve Makefile / CMake ([#19640](#))
- Fix at90usb1286 build ([#19687](#))
- Fix digipot compilation ([#19731](#))
- Fix mega2560ext environment ([#19730](#))
- More PIO dependencies optimizations
- Update ZMIB_V2 env names ([#19886](#))
- Permit spaces in dependencies g++ path ([#19929](#))
- PIO env for MKS Nano boards in STM32 ([#19905](#))
- Fix 0 extruders & bed compile ([#20030](#))
- Sanity-check illegal native USB ([#20047](#))
- Optimized (non-optiboot) Melzi env ([#20021](#))
- Windows LPC Upload for non-admins ([#20208](#))

- Fix STM32F1 ' freeMemory()' warnings ([#20319](#))
- Update to STM32 v10, optimize build ([#20325](#))
- Fix up start, monitor baud ([#20326](#))
- Require a minimum PlatformIO version ([#20361](#))
- Use a newer LPC176x framework ([#20469](#))
- Check for misplaced configs on build ([#20599](#))
- Set `build_flags` via `custom_marlin.FEATURE` ([#20692](#))
- Silence unused parameter warnings
- Compile fewer extraneous sources ([#20822](#))
- USB Flash Drive env hints for Auto Build Marlin ([#20592](#))
- Replace `lib_deps` for `custom_marlin.FEATURE` ([#20858](#))
- Update platform ststm32 ([#20928](#), [#21219](#))
- Let libmaple accept `RX / TX_BUFFER_SIZE` ([#21177](#))
- Fix LERDGE 'extends' env references ([#21305](#))
- Preflight checks for PlatformIO build ([#21068](#), [#21191](#), [#21361](#), [#21372](#), [#21658](#), [#21574](#))
- Misc build fixes ([#21413](#))
- Split up `platformio.ini` into `ini` folder ([#21507](#))
- Require PlatformIO >= 5.0.3
- Fix Rumba32 variant for Marlin ([#21497](#))
- Add 'jump relaxing' compile flag to AVR targets ([#21566](#))
- Fix Flash size (512KB) for STM32F103ZE ([#21590](#))
- Skip scripts during `platformio init` ([#21643](#))
- Let compiler do `Temperature.h` inlining

For Developers

- Bring " `mftest -a` " up to date with latest codebase
- Digipots refactor / cleanup ([#19690](#))
- Rename ultralcd => marlinui
- Internal G29N for G28 + G29 ([#20800](#))
- Pins post-process header ([#19860](#))
- Add `mfconfig` script used to manage configurations
- Add alternative ternary macros `IF_ENABLED` , `IF_DISABLED`
- Distinct runout states ([#19965](#))
- Add `parser.is_command(letter, code)`

- Local testing with `Makefile`, Docker, `mftest` ([#19981](#))
- Better USB Media Host conditions ([#20176](#))
- Adjust axis homed / trusted methods ([#20323](#))
- Avoid invalid memory optimizations ([#20389](#))
- More configurable animated bootscreen
- Homing feedrates as XYZ array ([#20426](#))
- Balance CI tests ([#20485](#))
- Add manual move type `ALL_AXES` for UBL mesh editing
- Fix and consolidate `PSTR` aliases ([#20812](#), [#20831](#))
- Move singlenozzle temp/fan ([#20829](#))
- Internal `G29N` code as shortcut for `G28\nG29`
- Clean up `MarlinCore` and `MarlinUI` ([#20832](#), [#20846](#), [#20852](#), [#20868](#), [#20869](#), [#20874](#))
- Init `KILL`, `SUICIDE`, `PSU` earlier ([#20810](#))
- No extra build folder for st/jlink upload ([#21341](#))
- Script to generate Marlin TFT Images ([#21340](#))
- Read extra ENVS from `pins.h` in preflight checks ([#21361](#))
- AutoReport class (Temperature, Cardreader) ([#20913](#), [#20959](#))
- Allow `mftest -t` to select test by number
- Add `-g3` to include macros in debug symbols ([#21052](#))
- Script to download & build Configurations ([#20992](#))
- Make `F_CPU` a compile-time constant ([#21051](#))
- Tweak tests, consolidate pins target validation ([#21254](#), [#21261](#))
- Script to generate Marlin TFT Images ([#21340](#))
- Added `typedef celsius_t` ([#21374](#), [#21678](#))
- Group UBL parameters in a structure
- More IntelliSense-friendly declarations
- Define HW serial ports needed for TMC UART ([#21446](#))
- Apply TMC UART to STM32, simplify
- Improve `uncrust` script
- Replace `const float &` with `const_float_t` ([#21505](#))
- `getHighESpeed => autotemp_task`
- Macros to eliminate '`f + 0.0`' ([#21568](#), [#21642](#))
- Drop return value from `Serial::write()` ([#21567](#), [#21577](#))
- Rename `tick()` to `isr()` to hilight interrupt-time

- Disable assert() by default with -DNDEBUG
- Add whole-degree accessors (#21685)
- Clean up / improve generate_version script (#21674)
- Add INO to .editorconfig
- Prettier output from opt_enable , et.al. (#21707)
- Drop compiler flag merge-constants due to GCC bug (#21711)



▶ Assets 2

Marlin 2.0.7.2

🏷 2.0.7.2 ➔ 88a2ac9

Compare ▾

thinkyhead released this on Oct 29, 2020

Issues Patched

- Define IS_ULTIPANEL properly for new configs
- Fix various errors, warnings in example config builds (#19686)
- Fix I2C_ADDRESS sign warning (#19685)
- Save PLR on resume from pause (#19676)

New Machines and Boards

- Add NUCLEO-F767ZI dev board (#19373)

New Features

- Add G34 Mechanical Gantry Calibration (like Prusa M915) (#18972)

Configuration

- Allow MAX31865 resistance values configuration (#19695)
- Add REPORT_TRAMMING_MM option (#19682)
- Sanity-check mutually-exclusive G34 features (#19706)

Board / HAL

- Fix HAL/STM32 FastIO for "A#" analog pins ([#19735](#))
- Restore correct STM32 port-bits code ([#19678](#))
- Fix SAMD Serial name macro ([#19765](#))
- Option to prevent (extra) Watchdog init on STM32 ([#19693](#))

LCD / Controller

- Improved TFT support ([#19192](#), [#19710](#))
- Prevent watchdog timeout in LVGL init ([#19724](#))
- Fix UTF8 handling for Color UI ([#19708](#))
- Fixes for TFTGLCD Panel, use FastIO ([#19614](#))
- Implement `wait_for_user` for Color UI ([#19694](#))
- Fix screen click reading too often ([#19696](#))

Optimized / Improved

- If needed, home before G34 ([#19713](#))
- Add loose soft endstop state, apply to UBL fine-tune ([#19681](#), [#19734](#))
- Digipots refactor / cleanup ([#19690](#))

Build and Upload

- Fix mega2560ext environment ([#19730](#))
- Fix motion compile w/out probe-oriented settings ([#19684](#))
- Fix AT90USB1286 build ([#19687](#))

For Developers

- Add `D100` Watchdog Test ([#19697](#))



▶ Assets 2

Marlin 2.0.7.1

↳ 2.0.7.1 → 11662bf

Compare ▾

 thinkyhead released this on Oct 10, 2020

Issues Patched

- Fix Ender-3 V2 Stop SD Print ([#19642](#))
- Fix Archim1 stepper timing (with new variant) ([#19596](#))
- Fix `Z_AFTER_HOMING` without probe ([#19607](#))
- Fix `TEMP_ADC_PROBE` support for STM32F1 ([#19582](#))
- Fix compile of MMU2 with S-mode disabled ([#19584](#))
- No move on Park = No move on Resume ([#19569](#))
- Fix Buzzer (pin) init for uninitialized FastIO ([#19559](#))
- Keep HAL tasks running during PID Autotune ([#19671](#))

New Machines and Boards

- FLY MINI ([#19185](#))

New Features

- Chamber servo vent, auto fan ([#19519](#))
- Z Probe Offset Wizard ([#18866](#))

Configuration

- Permit touch calibration override
- Move `SF_ARC_FIX` option to `Configuration_adv.h`

Board / HAL

- Use 0xFF (not 'ff') for SPI byte transfer
- Fix onboard SD card support for Teensy 3.6 & 4.1 ([#19593](#))
- Minor SPI fixes, `systick_callback` for STM32F1 HAL compatibility ([#19565](#))

LCD / Controller

- Update Slovak language ([#19561](#))
- Update Italian language ([#19654](#))
- Update German language ([#19615](#))
- Restore ° to 6x9 small info font ([#19645](#))

- Fix small font section directive, mixer warning
- Run language font data update
- Improve retract / unretreat labels
- Allow bypass for cold E movement ([#19606](#))
- Fix Tune/Fan edit items
- Touch UI support for X2, Y2 and Z2 ([#19538](#))
- Fix Anycubic i3 Mega target temperature display ([#19572](#))
- Fix Move Screen with disabled Touch ([#19558](#))

Host and Protocol

- G35 workaround for Pronterface "feature" ([#19577](#))

Optimized / Improved

- More accessible PROBE_OFFSET_WIZARD ([#19647](#))

Build and Upload

- Optional M42 / M226 ; Add more features filters ([#19664](#))
- Fix and improve Makefile / CMake ([#19640](#))
- Use env:mega2560ext for some boards ([#19624](#))
- Fix 'bossac' upload on Windows ([#19545](#))

For Developers

- Custom Debug Codes - Dnnn ([#19225](#))

Known Issues

- The M85 timeout might crash M600
- Possible layer shift (stepper DIR signal bug) on IDEX machines.



▶ Assets 2

Marlin 2.0.7

2.0.7 · e817773

Compare ▾

 thinkyhead released this on Sep 28, 2020

New Features

- "MarkForged" kinematics ([#19235](#))

New Machines and Boards

- MKS SGEN L V2 ([#18822](#), [#19462](#))
- STM32F1 EP with `USB_COMPOSITE` ([#19281](#))
- Teensy 4 ([#19311](#))
- MKS Gen L V2.1 ([#19314](#))
- MKS Robin E3P ([#19442](#))
- BigTreeTech SKR E3 Turbo ([#19500](#))
- Anycubic Chiron full feature support ([#19505](#))

Board / HAL

- Update HAL/STM32 platform to 8.0 ([#18496](#))
- Adjust GTR PeripheralPins to avoid timer conflicts ([#19183](#))
- LPC176x: Finish DMA transfer, use HW SPI class ([#19191](#))
- Fix Anycubic LCDs / Trigorilla 1.4 pins ([#19220](#))
- Fix STM32F1 SPI device init, `MKS_LCD12864` ([#19271](#))
- Emergency Parser for STM32F1 ([#19279](#))
- Raise STM32F1 UART IRQ Priority, add error handling ([#19301](#))
- Allow SWD debug on Robin Nano ([#19345](#))
- Ultratronics Pro SPI pins ([#19444](#))
- Replace Serial with Serial1 in pins files ([#19459](#))
- MKS Robin Mini uses `ONBOARD_SPI_DEVICE` ([#19460](#))
- Define UART pins for LPC debug based on `LPC_PINCFG_UART` ([#19475](#))

LCD / Controller

- Change "FR" on LCD to ">>" ([#18830](#))
- Update German, fix Mix component index ([#19206](#))

- Fix Anycubic I3 Mega (S) original screen % display ([#19210](#))
- Smoothieboard GLCD w/ SD support ([#19241](#))
- Fix Longer3D TFT defines, disable DMA ([#19251](#))
- Fix Touch UI long filenames, etc. ([#19262](#), [#19349](#))
- Fix Info Menu, Print Stats appearance ([#19348](#), [#19404](#))
- Fix extra string substitution bug ([#19351](#))
- Update Italian language ([#19365](#))
- MarlinUI for SPI/I2C TFT-GLCD character-based display bridge ([#19375](#))
- Move screen for Color UI ([#19386](#))
- Add warning to ExtUI Bed Mesh Screen. ([#19397](#))
- SHOW_REMAINING_TIME for HD44780 character LCD ([#19416](#))
- TFT: No timeout on Move Screen ([#19426](#))
- New Touch UI buttons ([#19465](#))
- Improve LVGL UI ([#19442](#))
- Allow ColorUI color customization ([#19484](#))
- Fix MBL "Click to continue" on Color UI touchscreen ([#19514](#))
- Working LCD_USE_DMA_FSMC ([#19522](#))
- Various updates for Ender 3 V2 controller:
 - No "Bed Leveling" item on Ender 3 V2 for manual probing
 - Highlight Creality DWIN menu icons ([#19368](#))
 - Revert LCD language to English on next boot
 - Add more DWIN commands, docs ([#19395](#))
 - Use F() for Ender 3 V2 DWIN strings
 - Other Ender 3 V2 (DWIN) issues ([#19441](#), [#19268](#))

Other Peripherals

- Fix Power-Loss Recovery for Ender 3 V2
- Fix Separate Neopixel ([#19179](#), [#19224](#), [#19250](#), [#19280](#), [#19287](#), [#19303](#))
- Read from backup TMC StealthChop state ([#19364](#))
- Fix Allen Key Probe pin test ([#19520](#))
- Add sensor for Kiss3d Silicone heater + precision cast plate ([#19528](#))

Host and Protocol

- Allow M524 between M23 and M24

- Escape the `M33` string arg ([#19515](#))
- Add Host Action: Start ([#19398](#))
- `M872` : Wait for Probe Temperature ([#19344](#))

Issues Patched

- Fix lost brightness during EEPROM load ([#19485](#))
- Fix "too cold" in `M600` ([#19332](#))
- Fix and improve STM32F1 serial ([#19464](#))
- Fix case light brightness save/load ([#19436](#))
- Fix compile with Danish, Basque ([#19325](#))
- Fix CoreXY compile with backlash calibration ([#19422](#))
- Fix Creality V4 SD Detect
- Fix `diveToFile` with open Dir object ([#19539](#))
- Fix EXP2 pin define for MKS SGEN_L ([#19369](#))
- Fix `M166` Gradient Mix for DELTA ([#19285](#))
- Fix missing `BOARD_K8800` ([#19331](#))
- Fix SKR 1.4 thermistor pin comments ([#19510](#))
- Fix UBL 'G29 I' for large meshes ([#19231](#))
- Fix up K8800 pins ([#19476](#))
- Fail SD mount without SPI re-init ([#19226](#))
- No 'Is' if media isn't mounted

Optimized / Improved

- Only show "SD Init Fail" with detectable media ([#19236](#))
- Make `M600` heat up the nozzle. Reset runout on fail. ([#19298](#))
- Improve temperature runaway, idle timeout ([#19339](#))
- Only set up SPI pins as needed ([#19372](#))
- MMU2 S Mode spins the BMG gears during `c0` ([#19429](#))
- Misc. Power-Loss Recovery improvements ([#19540](#))

Configuration

- Warning if `SDCARD_READONLY` should be disabled
- Permit touch params override w/ Robin nano ([#19196](#))

- Clarify disabling StallGuard for axes ([#19263](#))
- Sanity-check `BABYSTEP_DISPLAY_TOTAL` with ColorUI ([#19284](#))
- More configurable E3 V2 DWIN ([#19384](#))
- Expose `JOYSTICK_DEBUG` to general users ([#19394](#))
- Demo and test multiple PID defaults ([#19413](#))
- Optional Host Start menu item ([#19443](#))
- Optional menu item for Assisted Tramming ([#19447](#))
- Catch TMC address conflicts early ([#19458](#))
- Temp sensor for Kis3d Silicone heater + precision cast plate ([#19528](#))
- Cleanup of to configuration comments and formatting
- Sanity check old serial names

Build and Upload

- Fix AnyCubic LCD dependencies
- Warn in `platformio.ini` about RCT6 512K ([#19312](#))
- Fix compile for Taz Pro ([#19424](#))
- Include `pins.h` in dependency check ([#19468](#))
- Fix MKS Robin undefined pins error ([#19507](#))

For Developers

- Add extra `CardReader` debugging
- Add `CardReader::fileExists` (also updates the long name)
- Tweaks to git helper scripts
- New names for LCD conditionals ([#19533](#))

Known Issues

- The `M85` timeout might crash `M600`
- Possible layer shift (stepper DIR signal bug) on IDEX machines.



▶ Assets 2

Marlin 2.0.6.1

2.0.6.1 · ca194ca

Compare ▾

 thinkyhead released this on Aug 28, 2020

New Features

- Use `Z_AFTER_DEACTIVATE` to account for gravity ([#18906](#))
- Support for the Ender-3 V2 W25QXX EEPROM ([#18897](#))
- Password via G-code and MarlinUI ([#18399](#))
- `NOZZLE_CLEAN_NO_Y` for X-mounted cleaning station ([#18870](#))
- Independent second Neopixel strip option ([#19115](#))

Configuration

- Fix WiFi / ESP32 sanity check ([#18808](#))
- Clarify Nozzle-to-Probe offset ([#18828](#))
- Fix URLs to websites and resources ([#18844](#))
- SanityCheck: No Adafruit NeoPixel for STM32F1 ([#18833](#))
- Assisted Tramming requires a probe ([#18912](#))
- Increase Manual E Move Feedrate to 2mm/s ([#18937](#))
- HW PWM sanity checks for `SPINDLE_LASER_FREQUENCY` ([#18947](#))
- `EVENT_GCODE_SD_STOP => EVENT_GCODE_SD_ABORT` ([#18978](#))
- Clarify units in various places ([#18993](#))
- Checks for `CR10_STOCKDISPLAY` with Creality v4 ([#19019](#))
- Default Filament Runout Sensor enabled state ([#19013](#))
- Configurable number of M106 fans ([#18883](#))
- Use HIGH/LOW naming for some pin state settings ([#19089](#))
- Fix probing margin sanity-check

New Machines and Boards

- FYSETC S6 2.0 ([#19140](#))

Board / HAL

- Add `TEMP_PROBE_PIN` for Einsy Rambo ([#18823](#))
- Add Chitu 3D V6 2nd Filament Runout pin ([#18922](#))

- Fix Robin nano z_DIR_PIN conflict ([#18832](#))
- Fix Duplicator i3 Plus pin diagram ([#18862](#))
- Fix FLYF407ZG pins ([#18865](#))
- ZoneStar Z6FB ([#18918](#))
- Creality3D v4.2.7 ([#19088](#))
- DIGIPOT_I2C pins for SMOOTHIEBOARD ([#19098](#))
- Fix SD pins for SKR Pro and GTR ([#19047](#))
- Add Einsy Rambo Filament Runout Pin ([#19136](#))
- Fix Creality V4 probe pin

LCD / Controller

- Support for TFT & Touch Screens ([#18130](#))
- SPI Emulated DOGM (like FSMC_GRAPHICAL_TFT, but SPI) ([#18817](#))
- Fix Cancel Objects index display (zero-based) ([#18841](#), [#18930](#))
- Translatable strings on Ender-3 V2 DWIN ([#18893](#), [#19053](#))
- Fix MKS Nano v1.2 FSMC display ([#18901](#))
- More Anycubic + Trigorilla mappings, ExtUI ([#18903](#))
- Update Italian language ([#18886](#))
- Update Slovak language ([#18884](#))
- Make ILI9341 rotatable (e.g., Anycubic Predator) ([#18877](#), [#19010](#))
- Fix / optimize FSMC init ([#18941](#))
- Marlin Color UI for STM32F1 (SPI and FSMC) ([#18952](#), [#18958](#))
- Remaining Time for LIGHTWEIGHT_UI ([#18875](#))
- Fix Ender-3 V2 DWIN with manual mesh, host prompt ([#18981](#))
- For FTDI800 compatibility, remove VERTEX_FORMAT dependency ([#18982](#))
- MKS Robin new 320x240 TFT Color UI support ([#18985](#))
- Translated String interpolation for 2-digit numbers ([#18998](#))
- Optimize LVGL with HAL TFT IO (SPI and FSMC) ([#18974](#))
- ENDER2_STOCKDISPLAY for BTT SKR 1.4 (and Turbo) ([#19002](#))
- Show "SD init fail" status error ([#19064](#))
- Fix Select Screen "cancel" button destination
- Fix up the Mixer menu appearance
- Emulated DOGM via HAL TFT, XPT IO ([#19017](#))
- Use G28 0 optional homing in LCD Repeatability Test ([#19104](#))

- GRAPHICAL_TFT_ROTATE_180 for ST7789V ([#19042](#))
- Permit ST7789V orientation override ([#19044](#))
- TFT32 for MKS Robin Nano 1.2 ([#19031](#))
- Fixes to FTDI Touch UI ([#19134](#))
- TFT (plus Hardware SPI) for LPC176x ([#19139](#))

Other Peripherals

- New option to arrange Neopixel sets in series ([#18992](#))

Host and Protocol

- Broadcast SD Print Completion ([#19102](#))
- Updates for G6 Direct Stepping ([#19135](#))

Issues Patched

- Fix garbled print_xyz output ([#18810](#))
- Fix DELTA + TMC sensorless homing + SPI endstops ([#18811](#))
- Fix NEOPIXEL_LED compile w/out PRINTER_EVENT_LEDS ([#18824](#))
- Fix UNKNOWN_Z_NO_RAISE in G28
- Fix HEATER_0_PIN check with 0 EXTRUDERS ([#18827](#))
- Fix Spindle/Laser PWM DC ([#18871](#))
- Fix Z height after tool change ([#18951](#))
- Fix DISABLE_[XYZE] handling ([#18970](#))
- Fix 'sync_plan_position' call ([#19016](#))
- Do a runout.reset after EEPROM read
- Wait for hotend temp before Resume move ([#19009](#))
- Fix IS_PROBE_PIN test macro ([#19024](#))
- Fix PSU power-on for PID autotune ([#19066](#))
- Fix DUET_SMART_EFFECTOR
- Fix auto-power in PID autotune ([#19119](#))
- No COM_PIN needed for Ender-3 V2 display plus probe
- Fix SINGLENOZZLE fan speed bug ([#19152](#))
- Fix potential stack corruption in Move Menu

Optimized / Improved

- SAMD51 Endstop Interrupts ([#18836](#))
- SPI Flash data compression ([#18879](#))
- Shorthand values for M575 B Set Baud Rate
- Let laser/spindle use free AVR servo timers ([#19011](#))
- Prefer Servo AVR timer4 over 3 ([#19025](#))
- Small rework of axis homed / trusted handling ([#18907](#))

Build and Upload

- Improve dependency filter for faster builds ([#18919](#), [#18935](#), [#18960](#))
- Tailor the PlatformIO serial monitor
- No mks_robin extra_scripts in Trigorilla build ([#18872](#))
- Update build script for PIO 4.4 ([#19034](#))
- Env mega2560ext adds pins 70-85 ([#19022](#))
- Add custom_verbose, custom_gcc flags for native / simulator builds

For Developers

- Use uintptr_t for pointer-to-int conversion
- Fixed the hex_print function
- Fixed shell scripts that use gawk and wget
- Miscellaneous CI / git helper script improvements
- Move ExtUI displays to sub-folder ([#19070](#))
- Post a warning about MARLIN_DEV_MODE

Known Issues

- The M85 timeout (still) might crash M600 .
- Very long filenames on the SD card might cause instability with some LCD controllers.
- Mixing Extruder machines may freeze when an active Gradient updates the mix.



▶ Assets 2

Marlin 2.0.6

2.0.6 · 92076c6

Compare ▾

 thinkyhead released this on Jul 26, 2020

For this release we focused on compatibility with a wider range of boards and controllers, especially STM32-based boards, color screens, and touch screens. With so many new files being added, a lot of work has gone into optimizing the PlatformIO build by peeking at enabled features and only downloading libraries and compiling code required for your enabled options. And we tackled a whole host of issues from stepper timing and interrupt priority down to the details of controller-wheel responsiveness.

New Machines and Boards

- BigTreeTech SKR Pro 1.2
- Malyan M200 V2
- Malyan M300
- Creality Ender 3 V2 board (Creality v4.x)
- MKS Robin E3 / E3D
- MKS Robin nano V2
- BTT SKR Mini E3 V2
- Funmat HT V4.0
- Ortur 4.3
- Tenlog D3 Hero
- MEEB 3DP
- Tronxy X5SA (V5 / V6 boards)
- Vertex Nano with Velleman K8600
- Trigorilla Pro

New Features

- G6 External Motion Controller (like Klipper) support. See [#17853](#).
- Prusa MMU2 Extruder Sensor support
- Add settings for Prusa MMU2S
- Inline laser / spindle power control
- Add `M150 I` to set an individual Neopixel's color
- Automatic Tool Migration (beta). See [#17248](#)
- Composite USB for STM32 SDIO (experimental)

- `M600 R` to resume at a new temperature
- Optional move-to-center after UBL G29 J (3-point)
- Trinamic driver serial multiplexing
- Add `M122 I` to reinitialize TMC drivers at any time
- Option to enable `M360` for Repetier Host
- `M115_GEOMETRY_REPORT` adds machine info to `M115`
- Add `HOTEND_IDLE_TIMEOUT` **safety feature**
- Add `M200 S` and `L` for Volumetric Extruder Limit
- Add `G35` Bed tramping assistant
- Sensorless Homing for Core kinematics
- Power monitor and display. ([#17437](#))

Configuration

- Add `USE_PROBE_FOR_Z_HOMING` option
- Add `SERIAL_FLOAT_PRECISION` option
- Add `SD_PROCEDURE_DEPTH` option (for `M32 P`)
- Add `JD_HANDLE_SMALL_SEGMENTS` option. ([#18316](#))
- Add `REPORT_FAN_CHANGE` option
- Add `CONTROLLER_FAN_IGNORE_Z` option
- Change `FIL_RUNOUT_INVERTING` true to `FIL_RUNOUT_STATE HIGH`
- Use Material Preset 1 as defaults for `M303` PID autotune
- Allow different Default PIDs for each hotend
- Option to set Babystep Size in mm
- Trinamic steppers Homing Phase. See [#17299](#).
- Add a TMC Chopper Timing Preset for 24V 0.9°
- Homing bump is now an array
- Improved, extended "digipot" settings
- Add `AUTOTEMP` default proportions
- Adjustable `XY_FREQUENCY_LIMIT`
- `NOZZLE_PARK_FEATURE` X-only / Y-only move option
- Fix overridden U8G+SPI delay overrides
- Fix EEPROM type selection and fallbacks
- Add `SDCARD_READONLY` option to reduce binary size
- Add `VOLUMETRIC_EXTRUDER_LIMIT`. See [#17017](#).

- Add NOZZLE_PARK_Z_RAISE_MIN option
- Add sanity-check for Nozzle Park position
- Use Preheat 1 temperature as M303 default
- More Probe Temperature Compensation options
- Add xyz_no_FRAME option for Graphical LCD
- Allow larger ADC button debounce values
- Configurable kill pin state
- Change default filament diameter to 1.75mm
- Fix, clarify LCD_TIMEOUT_TO_STATUS
- Longer default power-up delay
- Disable Z stallGuard by default
- Allow CASE_LIGHT_PIN override from config
- Sanity check 3-point defines
- Sanity-check Chamber thermistor pin
- Add thermistor 502 for Zonestar Prusa P802M
- Use center XY for Z Safe Homing default
- Independent X2,Y2,Z2,Z3,Z4 endstop inverting
- Add a custom nozzle wipe G-code option

Board / HAL

- Fix BTT SKR Pro 1.0 issues
- Fix BTT GTR 1.0 issues
- Fix MKS S-Gen standard pins
- Fix FYSETC_AIO_II build
- Fix Fysetc stm32flash usage
- Fix FYSETC Cheetah issues, SD re-insert
- Fix MKS Robin nano issues, use Flash EEPROM
- Fix GTM32 Rev B LCD pins
- Fix BIQU BQ111-A4 pins
- Fix RAMPS 1.4.4 filament runout pin
- Increase STM32F1 Servo Timer Interrupt Priority
- Add Chitu V5 (with extra GPIO init)
- Add Chitu V6 (with Z2 stepper pins)
- Add Lerdge S,X,K boards

- Add Emergency Parser for the STM32 HAL
- Various Mightyboard improvements
- More complete RUMBA32 support
- Permit more Creality pin overrides
- Improve DIAG pin endstop management
- Various SAMD51 (AF Grand Central) improvements
- Add ReARM SDSS pin (for RRD LCDs)
- SD detect override for older Creality3D RAMPS
- Add Servo and E1 pins for the PICA board
- Allow timers to be set by STM32 pins files
- Improved STM32 timer allocation and prioritization
- Support TMCStepper with MKS Robin Pro
- Declare extended STM32 serial ports
- Add LPC176x SPI / I2C EEPROM support
- Add board-based ST7920 delays
- Fix STM32F103VE Flash EEPROM size
- Use MCP4451 interface for MKS SBASE
- Support GT2560 3rd extruder
- Consolidate MKS Robin / SKR Mini E3 pins
- Allow SDIO clock/retry overrides. See [#18223](#).
- Patch BLTouch z_MAX_PIN for GT2560 Rev.A (non-plus)
- Support BL24C16 EEPROM in HAL/STM32F1 (Ender 3 V2)

New LCDs and Controllers

- TFT LVGL UI
- FTDI EVE Touch UI
- Ender 3 V2 controller
- MKS UI / Little VGL TFT ([#18438](#))
- FYSETC TFT81050 LCD
- FYSETC 2.42 inch OLED
- MKS LCD12864 A/B Controller
- TFT 2x-3x scale for Anycubic, TronXY
- ExtUI support for Anycubic I3 Mega
- Touch-select for MarlinUI menu items

- Touch-to-jog for MarlinUI edit items
- Support for FT81050 to FYSETC F6

LCD / Controller

- Improved alert for EEPROM errors
- MarlinUI support for up to 5 Material Presets
- Suppress the initial SD status message
- Fix, extend, and improve ExtUI touch screens
- Fix LCD throttling issues
- Fix Graphical Display cosmetic issues, progress bar
- Fix low contrast on Minipanel display
- Implement MarlinUI for color touchscreens
- Display status during PID Autotune
- Add M73 remaining time for MKS UI
- Fix DGUS serial buffer size and other issues
- Fix GTR 1.0 CR-10 stock display pins
- Fix Silvergate GLCD display timing
- Fix Fan Speed menu items
- Fix click sound with TOUCH_BUTTONS
- Fix leveling "Point n of 3" message
- Add Bed PID Edit and Autotune menu items
- Move Case Light to LEDs submenu
- Remove "Media Released" message
- Shorter BLTouch menu item titles
- Add HD44780 mapping for Czech accents
- Bring language fonts up to date
- Clean up LCD Manual Move / UBL Mesh Edit
- ExtUI mesh support for Malyan LCD
- Add UI and TMC stall reset for multi-axis
- Add menu items to run G425 and G35
- Add Romanian language
- Updated languages:
 - English
 - Chinese

- French
- Galician
- German
- Hungarian
- Italian
- Polish
- Brazilian Portuguese
- Romanian
- Russian
- Slovak
- Spanish

Other Peripherals

- SKR Pro 1.1 WiFi / external SD card
- Flash-based EEPROM for Robin E3D
- Adjust Melzi ST display timing
- Store Case Light brightness in EEPROM
- Add Zonestar P802M bed thermistor
- Fix BLTouch early deployment with ABL G29
- For L64XX M17 can use hardStop
- Extend thermistor 1047 to 500°C

Host and Protocol

- Respect backspaces in G-code
- Real build date in M115 report
- Add M303 D to enable/disable PID debug output
- Add G12 E to set soft endstops state
- Allow M421 to modify a row, a column, or all
- More verbose probing error
- Prefix M503 output with echo:
- Fix some Host Actions issues
- Broadcast actions to all "hosts"
- Report fan speed on change
- Fix SD finished ExtUI / host action

- Fix M710 output formatting
- Separate G-code line numbers for each serial port
- Tweaks to M114 D output
- Fix Host Actions support with LPC176x
- Fix lingering Filament Change host dialog
- New M115 capabilities:
 - Cap:LONG_FILENAME
 - Cap:SDCARD
 - Cap:ARCS
 - Cap:BABYSTEPPING
 - Cap:RUNOUT

Issues Patched

- Fix BLTouch PWM reliability on STM32
- Fix Filament Change lengthy wait for heating
- Fix Due wired EEPROM init
- Fix ESP01 (module) WIFI initialization
- Fix CoreXY babystepping and homing
- More reliable double-click detection
- Fix extra TMC serial begin calls
- Fix M42 M with other parameters
- Fix M43 analog pins
- Fix position sync on M420 S0
- Fix G2 / G3 Arcs segment bugs
- Fix LPC176x RGB NEOPIXEL startup
- Fix issues with probing margins
- Fix G76 probe height / position
- Fix detection with multiple Filament Runout sensors
- Fix Mixer virtual tools reset
- Fix Power Loss Resume when card isn't mounted yet
- Fix false alarm interrupting probing
- No extraneous pins with ADC Keypad
- Fix Probe Temperature Compensation build
- Fix PID autotune timeout

- Fix Power Loss Resume with `HAS_LEDS_OFF_FLAG`
- Fix `G12` for `SINGLENOZZLE`
- Fix Max Jerk and Stepper PWM menus
- Fix XY Frequency menu
- Save/restore leveling on toolchange with `SINGLENOZZLE`
- Fix BTT002 SPEAKER timer conflict
- Fix STM32F4 flash / servo conflict
- Reserve 'probing failed' for the last attempt
- Fix SD printing pause with parking
- Fix multiplication/division for `xyz_pos_t`, *et.al.*
- Bring thermistor names up to date
- Ignore spurious thermocouple errors
- Fix alignment of 3-point leveling points
- Fix `G34` move in wrong direction
- Fix Malyan LCD crash bug
- Allow TMC Stall Sensitivity to be set to 0
- Fix `M125` unretract length
- Fix `M261`, i2c EEPROM, i2c Encoder on LPC176x
- Fix E DIAG pins for multi-axis auto-assignment
- Fix STM32F1 EEPROM access start
- Confirm XY position before Z Safe Homing
- For `G28 z` with Safe Homing, raise before move to XY
- Fix `SD_FINISHED_RELEASECOMMAND` bug
- Fix extra call to `unskew()`
- Limited backlash editing for Core kinematics
- Support up to 8 Trinamic E drivers
- Apply `HOME_BEFORE_FILAMENT_CHANGE` if any axis is unknown
- Consider `HOME_AFTER_DEACTIVATE` for Z safe homing
- Improve reliability of `POWER_LOSS_RECOVERY`
- Fix User Temp Sensor (1000), reversed Pt100 / Pt1000
- Fix Hotend Idle Timeout trigger ([#18657](#))
- Fix passive Chamber Temp reading
- Fix SD reverse sorting
- Fix `PSU_POWERUP_DELAY` when over 2 seconds

- Improve SAMD51 Servo / BLTouch PWM reliability

Optimized / Improved

- Reduce Step Smoothing ceiling to 50% CPU usage
- Improved Junction Deviation with lookup table
- More accurate Junction Deviation fast-acos
- Improve G2 / G3 motion accuracy
- Improve UBL Mesh Editor behavior
- Improved support for no bed / hotends / fans
- Reorder Marlin setup() and init serial early
- Minor Toolchange improvements
- EEPROM Flash Leveling for more STM32F4 boards
- Relax bed cooling safety check
- Save/Load distinct TMC Stallguard thresholds
- Better ooze prevention during pause
- Consider Chamber also in Print Job Timer auto-start
- Non-blocking MAX7219 init sequence
- MAX7219 pause / resume for interrupt-safe usage
- Minor optimizations in SD file listing
- Handle SD sort order in CardReader
- More conservative Trinamic DIR delay
- Add M32 subcall overflow error message
- Prevent setting temperature target outside sensor range
- Avoid excess E DIR changes in Linear Advance ([#18744](#))

Build and Upload

- platformio.ini specifies library versions to prevent unexpected build errors
- PlatformIO will only download and build libraries needed for enabled features
- Randomize name of firmware...bin in Ender 3 V2 build
- Allow HAL_TIMER_RATE override for STM32
- Fix CMSIS / USB-FD name conflicts
- Use "extends" in platformio.ini for better organization
- Get more lib_deps from the PlatformIO registry
- Fysetc S6 variant with direct DFU upload

- Use "melzi" envs for `MELZI_CREALITY` board
- Add a Chitu variant for disk-based update
- Use TMCStepper 0.7.0 for best LPC176x support
- Sanity check `SERIAL_STATS` options for LPC, STM32
- Use `STM32F407VGT6` for BTT002 V1
- Fix Archim PIO upload on Windows, Arduino IDE LCD
- Fix Archim LCD with Arduino IDE
- Fix Sanguino/1284p `board_upload.maximum_size`

For Developers

- The `ENABLED` / `DISABLED` macros are now usable in code
- Add "`TERN`" macros for conditional one-liners
- Allow pins to override `TIMER_NUM` and `HAL_TIMER_ISR`
- Add `uncrust` script/config for uncrustify source formatting (beta)
- Add `pinsformat.js` script to format pins files (beta)
- Add Git attributes specifying UNIX line endings
- Refine EEPROM types and manage in `HAL/*/inc/Conditionals_post.h`
- Add "Bed" / "Chamber" string substitutions
- Add a script to put identifiers on Configurations
- Add GitHub Actions to label, close, and lock issues
- Add SRAM command string injection
- Allow more parameters in `SERIAL_ECHO*PAIR` macros
- Define HAL ADC resolution in terms of bit-width
- Ensure `language.h` include order
- Fix `I2C_ADDRESS` ambiguity
- Move `tests` folder up (to `buildroot/tests`)
- Add pulldown items for all FastIO headers
- SD-detect handling refactored to `CardReader`. See [#17380](#)
- Allow for `STEPPER_TIMER_RATE` calling a function
- Use `MARLIN_EEPROM_SIZE` with `E2END` as fallback
- More customizable DGUSDisplay ([#18700](#))

Known Issues

- The M85 timeout might crash M600
 - M600 after starting SD print but before heating is complete is not supported.
-



▶ Assets 2

[Previous](#) [Next](#)